

Cost.

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: Jackson Lum

Examiner: Abdullahi Elmi Salad

Patent No.: 7,203,728

Group Art Unit: 2157

Date Issued: April 10, 2007

Docket: 812-2 CIP/CON II/CIP

POINT-OF-SALE SYSTEM AND

DISTRIBUTED COMPUTER NETWORK FOR SAME

Dated: August 2, 2007

Attn: Certificate of Corrections Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

I hereby certify this correspondence is being deposited with the United States Postal Service as first class mail, postpaid in an envelope, addressed to:

Commissioner for Patents, Alexandria, VA 22313-1450

20231 on August 2, 2007

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT PURSUANT TO 37 C.F.R. §1.322

Sir:

Please issue a Certificate of Correction in accordance with 37 C.F.R. §1.322 to correct the errors in the patent as set forth hereinbelow and on the enclosed copy of Patent Office Form PTO-1050. Form PTO-1050 is attached hereto in duplicate with at least one copy being suitable for printing.

In Column 8, Line 51

now reads "such that the 9 controller always" should read --such that the I/O controller always--;

Certificate

AUGO 8 2007

Applicants: Jackson Lum Patent No.: 7,203,728 B2 Issued: April 10, 2007

Page 2

Applicant submits that the errors marked above occurred through no fault of the Applicant. Accordingly, no fee is due.

It is respectfully requested that a Certificate of Correction be issued to correct the errors in the above-identified patent.

Respectfully submitted,

Rod S. Turner

Registration No.: 38.639 Attorney for Applicant

HOFFMANN & BARON, LLP 6900 Jericho Turnpike Syosset, New York 11791 (516) 822-3550 RST:dlb

277595_1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,203,728 B2

ISSUE DATE

April 10, 2007

INVENTOR(S)

Jackson Lum

It is certified that errors appear in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

IN THE SPECIFICATION:

In Column 8, Line 51

now reads "such that the 9 controller always" should read --such that the I/O controller always--;

MAILING ADDRESS OF SENDER Rod S. Turner HOFFMANN & BARON, LLP 6900 Jericho Turnpike Syosset, New York 11791

FORM PTO-1050 (REV. 3-75) (Modified) Copyright 1994 Legalsoft 277597

P15/REV01

PATENT NO. 7,203,728 B2

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,203,728 B2

ISSUE DATE

'April 10, 2007

INVENTOR(S)

Jackson Lum

It is certified that errors appear in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

IN THE SPECIFICATION:

In Column 8, Line 51

now reads "such that the 9 controller always" should read --such that the I/O controller always--;

MAILING ADDRESS OF SENDER Rod S. Turner HOFFMANN & BARON, LLP 6900 Jericho Turnpike Syosset, New York 11791

FORM PTO-1050 (REV. 3-75) (Modified) Copyright 1994 Legalsoft 277597

P15/REV01

119 8 2007